

FEDERAL ENERGY REGULATORY COMMISSION  
Office of Energy Projects  
Division of Dam Safety and Inspections - Headquarters Office  
888 First Street, N.E., Routing Code: PJ-13  
Washington, D.C. 20426  
(202) 502-6025 Office - (202) 219-2731 Facsimile

May 3, 2017

In reply refer to:  
P-2100

Mr. Ted Craddock  
Project Manager  
California Department of Water Resources  
P.O. Box 942836  
Sacramento, California, 94236-0001


Re: Forensic Review Team for Oroville Dam Spillway

Dear Mr. Craddock:

By letter dated March 20, 2017, Mr. John France, PE, D.GE, D.WRE, Mr. Henry Falvey, Mr. John Trojanowski, PE, Mr. Irfan Alvi, PE, Mr. Stephen Rigbey, and Mr. David K. Rogers, PE, CEG were accepted as members of the independent forensic review team for the Oroville Dam Spillway project. Your April 28, 2017, letter states that the selected geologist, Mr. Rogers, can't fulfill his role due to issues during the contracting process. You proposed Dr. Peter A. Dickson, P.G. as a replacement geologist for Mr. Rogers.

After reviewing Dr. Dickson's resume, he is accepted as a geologist for the Oroville Dam Spillway forensic review team.

Please contact me with any questions.

Sincerely,  


David E. Capka, PE  
Director, Division of Dam Safety  
and Inspections

cc: D2SI-HQ, D2SI-SFRO, Capka, Shannon

cc: Mr. David Panec  
Chief, Dam Safety Branch  
California Department of Water Resources  
P.O. Box 942836  
1416 Ninth Street, Room 604-9  
Sacramento, CA 94236-0001

Ms. Sharon Tapia, Chief  
Division of Safety of Dams  
California Department of Water Resources  
2200 X Street, Suite 200  
Sacramento, CA 95818